JETNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

Name of the officer 1 **Emin International Academy** Name of the School Kanhangad, Bekal.Pullur-Periya Location with name of Education Sub Dt. 1) 34,40x10.95x3.7m (GF) Classification building 4 2) 34,40x10.95x3.7m (FF) 3) 34.40x10.95x3.7m (SF) Period for which the Certificate issued 2023-24 Nature of defects if any No a) Foundation and basement b) Superstructure No c) Doors and windows No d) Wood work wrought and put up No No e) Roof No f) Flooring

g) Miscellaneous

Any major defects noticed which will render the building unsafe in any manner :

8 Whether maintenance works have been

done properly : Yes

 Whether the structure is sound for Conducting Classes. Yes, The structure is sound for conducting classes under normal weather conditions.

Remya TV, Assistant, Engineer, Pullur-Periya GP

NOTE: 1. Stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to floor etc.

2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate

Certified that the school was inspected by me on 25/12/2023 and found to be fit to conduct classes for the period 2023-24 for the reasons stated above.

No

Nil

Place: Chalingal

7.

Date: 25/12/2023

Signature and Designation

Assistant Engineer
USGO SECTION
PULLUR-PERIYA

